



Restoring the church clock

Peter Meecham and his assistant begin to dismantle the clock inside the bell tower of St Mary's. The clock drives both external clock faces by means of control rods and gear wheels.



Vital parts of the dismantled clock, which dates from 1910, will be cleaned and refurbished before reassembly.



Photos by Keith Williams
16th August 2019